

SAS Superstructure

Location: 04-SF-80-13.2 / 13.9 Client Name: CalTrans **Run date** 22-Nov-14 **Time** 8:21 AM

04-0120F4

04-SF-80-13.2/13.9

Self-Anchored

Suspension Bridge

Daily Diary Report by Bid Item

Contract No.: 04-0120F4

Diary #: 569 Const Calendar Day: 723
Inspector Name: Feather, Bernard

Date: 28-May-2014 Wednesday
Title: Transportation Engineer

Inspection Type: Intermittent

Shift Hours: 08:00 am 11:00 pm Break: 07:00 Over Time:

Federal ID: Location:

Reviewer: Shedd, Bill Approved Date: Status: Submit

Weather

Temperature 7 AM 12 PM 4PM

Precipitation Condition Not recorded

Working Day 🗹 If no, explain:

Diary:

General Comments

Track progress of FWS installation of reactivation air discharge plenum boxes under east anchorage, WB bridge. Track progress of FWS mechanical piping installation from a night closure of the WB bridge from the night of May 28, 2014 to the morning of May 29, 2014. Misc MEP paperwork and write diaries.

CCO-187 Bid	Item: 001	0-MSI-EFA.187	MEP/Structural Interferences	
SMITH-EMERY SF				
Labor				
Trade	Class	Name	RT Hrs OT Hrs DT Hrs Total Remarks	Dispute
Contractor: SMITH-	EMERY SF			
Certified Welding In:	s OTH	SALVADOR MERINO	4.00 0.00 0.00 4.00	
Diary:				Dispute
Dehumidification	n System	001 0-MS	SI-EFA.187	
	•			
			g inspection on the fabrication of the shim for the	
underside of the t	ower base	e denunumidification	unit per the direction given in the response to RFI 3643.	
CCO-187 Bid	Item: 001	0-MSI-EFA.187	MEP/Structural Interferences	
F.W. SPENCER AND S	ON, INC			
Labor				
Trade	Class	Name	RT Hrs OT Hrs DT Hrs Total Remarks	Dispute
Contractor: F.W. Si	PENCER AND	SON, INC		
Plumber/Pipefitter	JNM	NARCISO BIAGI	4.00 0.00 0.00 4.00	
Plumber/Pipefitter	FOR	TOM COLOMBO	4.00 0.00 0.00 4.00	
Diary:				Dispute
Dehumidification	n System	001 0-MS	SI-EFA.187	
	•			
			n Esquivel, went on shift at Pier 7 at 2000. The crew spe	ent
direction given in			shim for the tower base dehumidification unit per the	
-	,			
The crew used thi	ree crew t	rucks, a 2.5 HP gene	erator, and a 70 amp welding machine in the performance	Э

of this work.

Daily Diary Report by Bid Item

Job Name: 04-0120F4 Inspector Name Feather, Bernard Diary #: 569 Date: 28-May-2014 Wednesday

CCO-339	Bid I	tem:	001	0-MPI-ELS.	339	Modify Pi	ping at	PP128			
SMITH-EMERY	'SF										
Labor											
Trade		Class		Name		RT Hrs	OT Hrs	DT Hrs	Total	Remarks	Dispute
Contractor:	SMITH-E		SF								
Certified V	Velding Ins	ОТН		SALVADOR MERI	NO	3.00	0.00	0.00	3.00		
Diary:											Dispute
Bike Path	Mechar	nical		001	0-MPI-	ELS.339					
Expansion	n Loop										
Sal Marino spent 3 hours performing QC welding inspection on the attachiment of the shim for the 2 1/2" DW line PS-3 pipe support on the bottom side of the the PS-3 per the direction given in the response to RFI 3624.											
CCO-339	Bid I	tem:	001	0-MPI-ELS.	339	Modify Pi	ping at	PP128			
CERTIFIED CC	ATINGS (COMP	ANY								
Labor											
Trade		Class		Name		RT Hrs	OT Hrs	DT Hrs	Total	Remarks	Dispute
Contractor:	CERTIFI	ED COA	ATINGS	COMPANY							
Painter		JNM		GENIER VALDES		6.00	0.00		6.00		
Painter		APP		Victor Ruiz		8.00	0.00		8.00		
Painter		JNM		DANIEL DUIAN		6.00	0.00	0.00	6.00		
Diary:											Dispute
Bike Path	Mechar	nical		001	0-MPI-	ELS.339					
Expansion					•						
-	-	nt the	s ehif	t nerforming r	aint rer	air on th	e unda	reide c	of the F	Bike Path and the side of the	
				CCO 339 wo							
CCO-339			001	0-MPI-ELS		Modify Pi					
F.W. SPENCER				U-WIFI-ELS.	339	Modify Fi	piliy at	FF 120			
	Y AND 30	in, inc	,								
Labor Trade		Class		Name		RT Hre	OT Hrs	DT Hrs	Total	Remarks	Dispute
Contractor:	F.W. SPE		AND S			KIIIIS	011113	Dillis	Iotai	Remarks	Dispute
Plumber/P		JNM		NARCISO BIAGI		4.00	0.00	0.00	4.00		
Plumber/P	-	FOR		TOM COLOMBO		4.00	0.00	0.00	4.00		
D'											Disputo
Diary:											Dispute
Bike Path Expansion		nical		001	0-MPI-	ELS.339					
The lane c	losure ດ	f the	#5 lar	ne of the the	EB bride	ge was se	et up a	t 2300	on the	night of May 28, 2014. The	
										s in the closure at 2330, then	
	spent the second half of the shift welding the shims for the 2 1/2" DW PS-3 pipe supports to the underside										
							•			on given in the CCO 339 plan	
	sheets. The crew began demobilizing at 0230 on May 29, 2014, then went off shift at 0300 (per the pipe fitter's union agreement, the crew gets 8 hours of pay for 7 hours of work for overnight work).										
titter's unio	n agree	ment	, the (crew gets 8 h	ours of p	pay for 7	nours	ot work	k for o	vernight work).	
The crew used three crew trucks, a 2.5 hp generator, and a 70 amp welding machine in the performance of this work.											

Daily Diary Report by Bid Item

Job Name: 04-0120F4 Inspector Name Feather, Bernard Diary #: 569 Date: 28-May-2014 Wednesday

CCO-354	Bid	Item: 0	001	0-FWS-EL	S.354	CIC - Mec	nanical	mpacts	- F.W. S	Spencer	
F.W. SPENCER	AND S	ON, INC									
Labor Trade Contractor: Plumber/Pi	pefitter	Class PENCER A JNM FOR	ND SO	lame N, INC JARCISO BIAGI OM COLOMBO		RT Hrs 0.00 0.00	0.00 0.00	DT Hrs 0.00 0.00	Total 0.00 0.00	Remarks	Dispute
Diary: Mechanica	I Cha	nge of		001	0-FWS	S-ELS.35	4				Dispute
The mobiliz	ation	to and f	rom t	he bridge w	ill be pa	id under t	he CC	O 339	work f	or this shift.	
In addition to the equipment used in the performance of this work, the crew used a light tower and a towed port-a-potty which will be paid under CCO 354 via monthly invoice.											
CCO-365 F.W. SPENCER			001	0-CIC-EFA	365	CIC - Dehi	ımidific	ation Sy	stem		
Diary:	icatio	n Sveto	ım	001	٥-۵۱۵	-EEA 365					Dispute
Dehumidification System 001 0-CIC-EFA.365 Steve Gwizdak, Ygnacio Aranda, and Josh Kolotovich spent approximately 30 minutes to access the WB E2/E3 traveler from W2, then approximately 30 minutes to return to W2 following the work.											
CCO-372 F.W. SPENCER		I Item: 0	001	0-BDS-EF	A.372	Balancing	Dehum	idificatio	on Syste	ems	
Diary:											Dispute
Dehumidifi	icatio	n Syste	m	001	0-BDS	S-EFA.372	2				
Steve Gwizdak, Ygnacio Aranda, and Josh Kolotovich spent 6 hours installing the 12" x 12" louver and plenum box for the reactivation air discharge on the underside of the OBG under the east anchorage, WB splay chamber, per the direction given in RFI 118R04 through R07.											
The crew accessed the work location via the E2 elevator and E2/E3 traveler.											
The crew used small tools (electric drilles) in performance of this work.											
Bill O'Suulivan met with Scott Dossett, Munters, at at YBI at 0700. Scott then uploaded new software into Unit #1 (W2 pier cap), then headed to Unit 3 and 4 (WB and EB east end anchorage units, respectively) and uploaded of new software and verification of operation. The work took approximately 45 minutes for each unit, and another 60 minutes to go to the east anchorages, then return to W2 following the work. The new software is for additional coordination with SCADA and is beyond the scope of the the original contract.											